



SCHNELLBACHER - SENDON GROUP, LLC

Specialists In Exterior Building Restoration

Carlyle House
50 East 77th Street
New York, NY

Building Classification:

Residential Building
Steel Frame
Masonry Façade

Project Description:

Façade Restoration
Concrete Roof Slab Replacement
Roof Replacement
Paver Installation

Contract Amount:

\$ 3,050,000.00



259 Stephens Street, Belleville, New Jersey 07109

Tel: 973 759-4488 Fax: 973 759-4466